

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
01 0 1 0 R T N P 1 2 0 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5										LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT									
01 0 1 0 5 0 - 0 3 4 4 7 0 1 0 9 8 2 8 0 2 0 5 8 2 9										REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																			
02 FOLLOWING A REACTOR TRIP FROM 100% POWER, BOTH SOURCE RANGE INSTRUMENTATION																			
03 CHANNELS FAILED TO ENERGIZE WHEN THE REQUIRED PERMISSIVES WERE SATISFIED.																			
04 SHUTDOWN MARGIN WAS PROPERLY VERIFIED. THERE WAS NO EFFECT ON PLANT OR																			
05 PUBLIC SAFETY AS THE REACTOR WAS ALREADY SHUT DOWN.																			
06																			
07																			
08																			
09 1 1 A 11 E 12 E 13 I N S T R U 14 E 15 Z 16																			
17 8 2 0 0 2 0 3 L 0 0																			
E 18 F 19 Z 20 Z 21 0 0 0 0 0 0 Y 23 N 24 N 25 W 1 2 0 26																			
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																			
10 THE CAUSE OF THE OCCURRENCE WAS IMPROPER ACTUATION OF THE INSTRUMENT																			
11 CROWBAR CIRCUIT, A SURGE PROTECTION DEVICE. BOTH CHANNELS ENERGIZED																			
12 WHEN THE CONTROL POWER FUSES WERE REMOVED AND REINSERTED. STUDY OF THE																			
13 CIRCUIT DESIGN IS UNDERWAY.																			
14																			
15 D 28 0																			