

Southern California Edison Company

SCE

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

K. P. BASKIN

MANAGER OF NUCLEAR ENGINEERING,
SAFETY, AND LICENSING

February 11, 1982

TELEPHONE
(213) 572-1401

Director of Nuclear Reactor Regulation
Attn: D. M. Crutchfield, Chief
Operating Reactors, Branch #5
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington D.C. 20555



Dear Mr. Crutchfield:

SUBJECT: CE HEATED JUNCTION THERMOCOUPLE REACTOR VESSEL
MEASUREMENT SYSTEM

Your letter to me of January 27, 1982, as Chairman of the CE Owners Group, requests additional information regarding the CE Inadequate Core Cooling Instrumentation. The questions enclosed with your letter were identical to and part of a larger group of questions that was sent to CE in a letter from Robert Tedesco to Ed Scherer dated January 19, 1982. The letter to CE had 16 questions related to the CESSAR and under Docket #STN-50-470F.

The answers to your questions will be provided by CE in their response to your January 19 letter.

Sincerely yours,

KP Baskin

Chairman, CE Owners Group

cc: J. H. Hutton
CEOG Steering Committee

ED03
5/
110

8202180258 820211
PDR TOPRP EMVC-E
C PDR