



LER 82-001

CAUSE DESCRIPTION AND CORRECTIVE ACTION CONTINUED

All personnel involved have been counseled on the importance of adherence to the surveillance requirements of the technical specifications and of proper communications.

The hoist box has been shielded to reduce radiation levels below the alarm setpoint and Channel 7 ARMS is operable.