LICENSEE EVENT REPORT

O 1 M I D C C 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 0 4 5 5 CAT 58 5 CON'T O 1 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 1 REPORT L 6 0 5 0 0 0 3 1 5 0 0 1 2 3 8 2 8 0 2 1 9 8 2 9
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0] [WHILE PERFORMING A ROUTINE TOUR AN AUXILIARY EQUIPMENT OPERATOR DISCOVERED THAT THE
[0]3 LRECORDER (1-CS-001) USED FOR CONTAINMENT SUMP FLOW MONITORING WAS OUT OF PAPER. THIS J
O 4 CONDITION EXISTED FROM APPROXIMATELY 1415 HOURS UNTIL 2100 HOURS ON JANUARY 23, 1982.
[0]5 [THIS EVENT WAS CONTRARY TO THE REQUIREMENTS OF TECH. SPEC. 3.4.5.16. THIS IS THE
0 T6 FIRST OCCURRANCE OF THIS TYPE AND NO PROBABLE CONSEQUENCES RESULTED.
07
7 8 9
SYSTEM CAUSE CAUSE SUBCODE SUB
17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE COMPONENT NORTH ON PLANT ON PLANT ON PLANT METHOD HOURS 22 ATTACHMENT NORTH FORM SUBMITTED FORM SUBPLIER MANUFACTURER G 18 Z 19 Z 20 Z 21 C 9 0 0 N 23 N 24 N 25 E 3 3 0 2
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) TIOT I WHEN THE RECORDER WAS CHECKED DURING THE PREVIOUS SHIFT AS REQUIRED BY PROCEDURE IT WAS
LEUNCTIONING PROPERLY. AT THAT TIME IT WAS NOT OBVIOUS TO THE OPERATOR THAT THE AMOUNT
[1 12] LOF PAPER ON THE FEED ROLL WOULD NOT LAST FOR ANOTHER 8 HOURS. A NEW ROLL WAS PUT IN
THE RECORDER IMMEDIATELY. THE PROCEDURE HAS BEEN REVISED WITH INSTRUCTIONS TO CHANGE
TT4 LTHE CHART PAPER IF LESS THAN 3 FEET REMAINS.
FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 3 DISCOVERY DESCRIPTION 32 OPERATOR OBSERVATION 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41) DESCRIPTION 41
LOSS OF OR DAMAGE TO FACILITY 43
1 9 Z (42 NA 80 80 80 80 80 80 80 8
NAME OF PREPARER D. M. TAPER PHONE (616) 465-5901 ext. 1490