



ATTACHMENT to LER 82-004/03L-0

Item 10, Event Description and Probable Consequences - continued

Reportable per Technical Specification 6.9.1.13.b.

Item 27, Cause Description and Corrective Actions - continued

The oscillator was externally excited and functioned properly. Subsequent operability testing of the oily water separator system revealed inadequacies in Procedure STP I-78A. STP I-78A will be revised.