




United States Department of the Interior

BUREAU OF INDIAN AFFAIRS

ABERDEEN AREA OFFICE  
115 FOURTH AVENUE S.E.  
ABERDEEN, SOUTH DAKOTA 57401




IN REPLY REFER TO:

MAY 8 1990

United States Nuclear  
Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

License: 40-15053-01  
Docket: 30-08502790-01



Dear Sir:

This is in response to your letter of April 6, 1990 citing apparent violations of License Condition 16, 13.A.(1), 14 and the maintenance of personnel dosimetry records for 1988. The corrective actions that have been taken will be listed in the order in which the APPENDIX categorizes the violations.

1. The Victoreen Survey Meter has been calibrated and is now operable. Arrangements have been made to receive this service from the Brown County Civil Defense Director each year.
2. A better system has been initiated for maintaining leak test records in conjunction with inventory control of the various nuclear devices. All equipment has been factory repaired or tested for leakage within the last three months.
3. Covered in 2. above.
4. We have applied for a supplemental personnel dosimetry report for 1988 from our servicing vendor. We expect to have this report within 30 days.

We anticipate having our program in compliance with the license requirements by July 1, 1990. Should you have any questions or need additional information, call Gerry E. Foell, Area Road Engineer, (605) 226-7645.

Sincerely,

*Joseph L. Jaeger*  
Area Director

cc: Area Road Engineer, Code 307  
Area Construction Engineer, Code 307  
File

9005230354 800508  
REG4 LIC30  
40-15053-01 PDC

IC-90-147

110  
IC07