

231 W Michigan, PO Box 2046 Milwaukee Wi 53201

(414) 221-2345

VPNPD-93-103 NRC-93-062

May 14, 1993

Document Control Desk U.S. NUCLEAR REGULATORY COMMISSION Mail Station P1-137 Washington, DC 20555

Gentlemen:

DOCKET 50-266
LICENSEE EVENT REPORT 93-005-00
INADVERTENT ENGINEERED SAFETY FEATURE ACTUATION
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report 93-005-00 for Point Beach Nuclear Plant, Unit 1. This report is provided in accordance with 10 CFR 50.73(a)(2)(iv), "The licensee shall report...any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF)..."

This report describes the inadvertent actuation of an Engineered Safety Feature while adjusting the time delay relay setpoint for a containment accident fan.

Please contact us if there are any questions.

Sincerely,

Bob Link

Vice President Nuclear Power

KVA/jq

Attachment

cc: NRC Regional Administrator, Region III

NRC Resident Inspector

9305210050 930514 PDR ADDCK 05000266 PDR TERM



231 W Michigan, PO. Box 2046, Milwaukee, Wt 53201

[414] 221-2345

VPNPD-93-103 NRC-93-062

May 14, 1993

Document Control Desk U.S. NUCLEAR REGULATORY COMMISSION Mail Station P1-137 Washington, DC 20555

Gentlemen:

DOCKET 50-266 LICENSEE EVENT REPORT 93-005-00 INADVERTENT ENGINEERED SAFETY FEATURE ACTUATION POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report 93-005-00 for Point Beach Nuclear Plant, Unit 1. This report is provided in accordance with 10 CFR 50.73(a)(2)(iv), "The licensee shall report...any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF) ... "

This report describes the inadvertent actuation of an Engineered Safety Feature while adjusting the time delay relay setpoint for a containment accident fan.

Please contact us if there are any questions.

Sincerely,

Bob Link

Vice President Nuclear Power

KVA/jg

Attachment

cc: NRC Regional Administrator, Region III

NRC Resident Inspector