(7-94)

U.S. NUCLEAR REGULATORY COMMISSION

40 CFR 2.201	SAFETY	Page 1 of2_		
1 LICENSEE Veterans Administra 700 South 19th Stre Birmingham, AL 352		2. REGIONAL OFFICE REGION II U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION		
	01-00643-02	June 8-16, 1993		
Begulatory Commission (NRC) rule procedures and representative recitellows: 1. Within the scope of this in the scope of the scope o	es and regulations and the conditions ords, interviews with personnel and o inspection, no violations were observe d the steps you have taken to correct ins at this time.	the violations identified during the last inspection. We have no further		
	rtain of your activities, as described by which is required to be posted in acc	elow or attached, were in violation of NRC requirements. This form is a ordance with 10 CFR 19.11. was not properly posted to		
indicate the preser	nce of a	10 CFR 20.203(b),(c),(d),(e) or 34.42.		
B.				
		or License Condition Number		
C. Records of		were not properly maintained.		
10 CFR	10 CFR or License Condition Number			
D. Documents were n	Documents were not properly posted or otherwise made available. 10 CFR 19.11.			
E. Reports or notifical	tion of	were not made in accordance with		
10 CFR	or License Condition No	umber		
F				

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC

SIGNATURE LICENICEE DATE 9308060073 930708 PDR ADDCK 03001204 PDR

SIGNATURE -- NRC INSPECTOR

SAFETY INSPECTION

					Page 2 of Z	
1.	700 South	terans Administration Medical Center O South 19th Street rmingham, AL 35233		2. REGIONAL (DEFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323	
3.	DOCKET NUMB	ER(S)	4. LICENSE NUMBER		5. DATE OF INSPECTION	
	030-01204		01-00643-02		June 8-10, 1993	
	3. (Co	ntinued)				
G						
	Щ.					
	LJ					
X	entified, and corrective action was or is being taken, and the ed.					
	Z A	A written quality management program was not established and maintained to				
	lane and				terial and radiation from byproduct	
material would be administered as directed 1						
	П.	with 10 GFR 35.32(a)(1)(iii), (iv) and (v).				
[X] B Supervised individuals Were not instructed in the licen						
management progr			ram between Jan	nary 27, 19	92, and January 12, 1993, as required	
		by 10 CFR 35.25	(a)(1).			
	LEJC	On four occasio	ns, iodine-131	vaste vas d	prior isposedprimer to be period of ten	
		half-lives (80				
		Ancillary Detson	mel (security,	ianitorial	, varehouse, etc.) did not receive	
	b-reshoot "				ired by license condition 15.	