

APPENDIX A

NOTICE OF VIOLATION

Fischer Technology, Inc.  
Windsor, Connecticut 06095

Docket No. 030-17073  
License No 06-19165-01

As a result of the inspection conducted on June 9, 1993, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1993), the following violations were identified:

1. Condition 12 of License No. 06-19165-01 requires that sealed sources and detector cells containing byproduct material be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, as of June 9, 1993, a sealed source containing, nominally, 150 microcuries of thallium 204 had not been tested for contamination or leakage between May of 1992 and May of 1993.

This is a Severity Level IV violation. (Supplement VI)

2. 10 CFR 19.11(a) and (b) require that current copies of Part 19, Part 20, the license, license conditions, documents incorporated into the license, license amendments and operating procedures be posted, or that a notice describing these documents and where they may be examined, be posted.

Contrary to the above, on June 9, 1993, neither the documents nor the notices were posted.

This is a Severity Level V violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Fischer Technology, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY - S:\PENDING\FISCHER.RPT - 07/07/93

9308090077 930714  
PDR ADOCK 03017073  
C PDR