LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N 8 S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T    0   1   SOURCE   L   6   0   5   0   0   0   3   1   1   7   0   1   2   1   8   2   8   0   2   1   9   8   2   9     7   8   8   8   9   8   8   9   8   8   9   8   9   8   9   8   9   8   9   9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  O 2   On January 21, 1982, during the performance of the M3T maintenance surveillance test,
it was discovered that the undervoltage relay on the 2C vital bus was actuating at
55.5 volts instead of the 77.3 volt trip setpoint value. The relay was placed in the
tripped condition, and at 2050 hours Action Statement 3.3.2.a Action 14 was entered.
06
0 7
08
7 8 9  SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE  COMP VALVE SUBCODE SUBCODE
0 9   E B (1) E (12) A (13) R E L A Y X (14) B (15) Z (16)  7 8   SEQUENTIAL OCCURRENCE REPORT REVISION
17   LER RO
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER  E 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 L 26 G 0 8 0 26  33 34 42 43 43 44 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  1 0 Due to a similar occurrence with the same relay two months earlier, it was inspected
by both the Relay Department and the Energy Lab. No defects were found. The relay
was recalibrated and tested satisfactorily. The M3T surveillance test was satisfac-
torily performed. At 1040 hours, January 23, 1982 Action Statement 3.3.2.a was
1 4 terminated. (81-124)
FACILITY STATUS STATUS OTHER ST
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  1 6 Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  1 7 0 0 0 0 37 Z 38 NA  7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER DESCRIPTION (41)  1 8 0 0 0 0(40) NA
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (42)
T 9 Z 42 NA
PUBLICITY   SSUED   DESCRIPTION 45   PDR   ADOCK 05000311   S   PDR   PDR   S   PDR   S   S   S   S   S   S   S   S   S
NAME OF PREPARER Frank Dickey PHONE 609-935-0398