

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE I B 11		CAUSE CODE E 12		CAUSE SUBCODE F 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE E 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 8 2 21 22		SEQUENTIAL REPORT NO. 0 2 7 24 26		OCCURRENCE CODE / 27		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24	
PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 26											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 SRM B, Model No. 1123144G007, downscale indications are attributed to a failed  
1 1 monitor probe. A Work Request and Authorization to replace the detector during the up-  
1 2 coming refueling outage has been written. The SRM C pulse height discriminator ad-  
1 3 justment was out of specified tolerance. The pulse height discriminator was adjusted  
1 4 to function within specified tolerances and SRM C, Model No. 194X365G1, was returned to  
7 8 9 service. 80

NA

NRC USE ONLY

PHONE: 919-457-9521