11.111	LICENSEE EVENT REPORT
	CONTROL BLOCK: [ ] ] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5  B LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	SOURCE L 6 0 5 0 0 0 3 1 1 7 0 2 1 9 8 2 8 0 3 1 8 8 2 9
0 2	On February 19, 1982 No. 21 Steam Generator Level Channel 2 was reading 20% higher
0 3	than Channels 3 and 4. At 1740 hours No. 21 Steam Generator Level Channel 2 was
0 4	declared inoperable and Action Statements 3.3.1 Action 7 and 3.3.2.b Action 14 were
0 5	entered.
0 6	
0 7	
7 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9 7 8	CODE SUBCODE S
	LER RO EVENT YEAR SEQUENTIAL REPORT NO.  REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME GOMP. SUPPLIER MANUFACTURER    X   18   Z   19   Z   20   Z   21   0   0   0   41   23   12   42   43   45   44   47   47     CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	The channel bistable was placed in the tripped condition within one hour. The trans-
	mitter was tested and found satisfactory and in calibration. The sensing lines were
1 2	blown down to remove accumulated suspended solids. Channel 2 was tested satisfac-
1 3	torily and returned to service. At 0001 hours, February 20, 1982, Action Statements
7 8	3.3.1 Action 7 and 3.3.2.b Action 14 were terminated. (82-12, 81-105)
1 5	FACILITY STATUS  POWER  OTHER STATUS  OTHER
	CCTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  Z (33) Z (34) NA  NA  NA  NA  NA  NA
1 7 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  O O O 37 Z 38 NA  PERSONNEL INJURIES 80
1 8	NUMBER DESCRIPTION (41) O O O O NA
1 9	SO TO BE DAMAGE TO FACILITY (43)  TYPE DESCRIPTION  Z (42) NA
7 8	PUBLICITY SSUED B204020345 B20318 PDR ADOCK 05000311 PDR ADOCK 05000311 PDR 68 69 80 6
	NAME OF PREPARER Frank Dickey PHONE 609-935-0998