LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [[PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION]
0 1 T N S N P 1 2 0 0 - 0 0 0 0 0 0 0 4 1 1 1 1 1 0 57 CAT 56
CON'T REPORT L 6 0 5 10 10 0 3 2 7 7 0 0 2 1 5 8 2 8 0 3 1 6 8 2 3 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
O 2 At 0539 CST on 02/15/82 with unit 1 in mode 3, glycol containment isolation valve
0 3 1-FCV-61-194 would not reopen after it was stroked from the full open position. This
0 4 required entry into the action statement of LCO 3.6.3.1. There was no effect on
0 5 public health or safety. Previous occurrences - none.
06
07
7 8 9
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 1) REPORT NUMBER 8 2
ACTION FUTURE COMPONENT SHUTDOWN METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER SUPPL
Threstigation revealed that conductor GIB1 which controls the solencid was not
terminated during previous maintenance work on junction box 2270 on 01/30/82. The
[1] conductor was referminated. The valve was functionally tested and returned to
[1]3 service at 1500 on 02/15/82.
1,4
FACILITY STATUS STATU
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA 1 8 9 10 11 45
NUMBER TYPE DESCRIPTION 39 NA
PERSONNEL INJURIES NUMBER DESCRIPTION (1) NA NA
LOSS OF OR DAMAGE TO FACILITY (A)
TIP Z 42 NA
ISSUED DESCRIPTION (45)
S204020385 820316 PDR ADDCK 05000327
Name c S