

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1	L	0	5	0	0	0	2	5	9	1	1	1	2	8	1	0	3	1	6	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while performing SI 4.2.B-55 (RHR loop B discharge pressure)

0 3 1-PT-74-65 was found out of tolerance by 5.9%. (T.S. Table 3.2.B) This transmitter

0 4 indicates discharge pressure of RHR system II. There was no danger to the health

0 5 or safety of the public. Redundant systems were available and operable. There

0 6 were no previous similar events.

0 7

C 8

0	9	C	F	11	E	12	E	13	I	N	S	T	R	U	14	T	15	Z	16
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----

SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 12 13 COMPONENT CODE 13 18 COMP. SUBCODE 19 20 VALVE SUBCODE 20 21

17 LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32

ACTION TAKEN 33 34 FUTURE ACTION 35 36 EFFECT ON PLANT 37 38 SHUTDOWN METHOD 39 40 HOURS 41 42 ATTACHMENT SUBMITTED 43 44 NPD-4 FORM SUB. 45 46 PRIME COMP. SUPPLIER 47 48 COMPONENT MANUFACTURER 49 50

E 18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 L 25 G 0 8 0 0 26

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Instrument drift. The GE model 551 pressure transmitter was recalibrated,

1 1 functionally tested and returned to service. This is considered a random event

1 2 and no further recurrence control is required.

1 3

1 4

1	5	E	28	0	9	9	29	NA	30	B	31	Surveillance test.	32
---	---	---	----	---	---	---	----	----	----	---	----	--------------------	----

FACILITY STATUS 3 8 9 % POWER 10 11 OTHER STATUS 12 13 METHOD OF DISCOVERY 44 45 DISCOVERY DESCRIPTION 46 47

1	6	Z	33	Z	34	NA	35	NA	36
---	---	---	----	---	----	----	----	----	----

ACTIVITY TAKEN 33 34 CONTENT 35 36 AMOUNT OF ACTIVITY 37 38 LOCATION OF RELEASE 39 40

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

PERSONNEL EXPOSURES NUMBER 10 11 TYPE 12 13 DESCRIPTION 14 15

1	8	0	0	0	40	NA	41
---	---	---	---	---	----	----	----

PERSONNEL INJURIES NUMBER 10 11 DESCRIPTION 12 13

1	9	Z	42	NA	43
---	---	---	----	----	----

LOSS OF OR DAMAGE TO FACILITY TYPE 10 11 DESCRIPTION 12 13

2	0	N	44	NA	45
---	---	---	----	----	----

PUBLICITY ISSUED 10 11 DESCRIPTION 12 13

8204020498 820316  
PDR ADOCK 05000259  
S PDR

Gene Holder

PHONE (205) 729-6134