## LICENSEE EVENT REPORT

* CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 5 5 CAT 58
COM'T  C 1  REPORT L 6 0 5 0 - 0 3 2 4 7 0 2 2 7 8 2 8 0 3 2 4 8 2 9  TOWNS SOURCE L 6 0 5 0 - 0 3 2 4 8 2 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [0 2   During plant operation, it was discovered that suppression chamber water temperature
[0]3 [recorder, 2-CAC-TR-778, located on the remote shutdown panel, was showing normal,
0 4 expected indications of temperatures, but was not recording them on the chart recorder
Similar events involving this recorder have been reported in LERs 2-81-134, 2-82-10
o 6 and 2-82-17. This event did not affect the health and safety of the public,
07
Technical Specifications 3.3.5.2, 6.9.1.9b
SYSTEM CODE CAUSE CAUSE COMPONENT CODE SUBCODE
SEQUENTIAL REPORT NO.  17) REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  E 18 X 19 Z 20 Z 21 0 0 0 0 0 0 N 23 Y 24 N 25 B 4 1 5 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [1 0   The recorder print actuation solenoid was out of adjustment resulting in the event.
[1] [The solenoid was adjusted for proper operation and the recorder, Model No. 551, was
returned to service. To help prevent future similar events, this recorder will be re-
built following the receipt of replacement parts. Routine preventative maintenance on
this instruent is performed on a monthly basis.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 E 28 0 7 5 29 NA A A 44 45 46
ACTIVITY CONTENT RELEASED OF RELEASE  AMOUNT OF ACTIVITY 35 NA
PERSONNEL EXPOSURES  NUMBER  TYPE  O O O O O O O O O O O O O O O O O O O
PERSONNEL INJURIES NUMBER DESCRIPTION 41
LOSS OF OR DAMAGE TO FACILITY (43)  TYPE DESCRIPTION  NA  NA
8204080067 F320324 PDR ADDCK 0'5000324 PDR NA
M. J. Pastva, Jr. 919-457-9521