




Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 750
Hartsville, South Carolina 29550

MAR 26 1982

Robinson File No: 13510C



Serial: RSEP/82-542

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
LICENSEE EVENT UPDATE REPORT 79-34, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Report is submitted. The original report, October 5, 1979, described the failure of a motor operated isolation valve in the Auxiliary Feedwater System to close properly during the performance of a Periodic Test. This revision contains a complete description of the event with new information indicated by a vertical bar in the right hand margin. This report, therefore, supersedes and should replace all copies of the original Licensee Event Report.

Very truly yours,

R. B. Starkey, Jr.
General Manager
H. B. Robinson S.E. Plant

HTC/tm

Enclosure

cc: R. A. Hartfield (3)
R. C. DeYoung (30)

OFFICIAL COPY

1422
5/11

8204080373 820326
PDR ADOCK 05000261
S PDR