April 2, 1982

Mr. James G. Keppler, Regional Administrator Directorate of Inspection and Enforcement - Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137



Subject: Braidwood Station Units 1 and 2

50.55(e) Deficiency Report 82-01 NRC Docket Nos. 50-456 and 40-457

Reference (a): March 12, 1982, letter from T. R. Tramm to J. G. Keppler.

Dear Mr. Keppler:

This is to provide information regarding apparently reportable deficiencies in Pullman HVAC duct supports and stiffeners at Braidwood.

Reference (a) indicated that the final report on these deficiencies would be delayed. It is now apparent that the final report will be available by April 26, 1982. Duct erection has resumed based upon a preliminary review of the duct stiffener evaluation.

Please address any questions regarding this matter to this office.

Very truly yours,

T.R. Traum

T. R. Tramm

Nuclear Licensing Administrator

1 m

3784N