



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 - BEAUMONT, TEXAS 77704
AREA CODE 713 838-6631

April 1, 1982
RBG-12,389
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458

On March 2, 1982, Gulf States Utilities (GSU) informed Region IV of a deficiency potentially reportable under 10CFR50.55(e). The gap between the free end of a W24 X162 beam at azimuth 184, elevation 141'-0" and the drywell wall was found to be 1/4" where the minimum specified gap was 1 1/2". The deficiency has been corrected in accordance with Nonconformance and Disposition Report (N&D) 2193 dated February 25, 1982.

GSU's investigation to determine the significance of this deficiency with respect to reportability is not complete. GSU will provide a Status Report on this investigation by May 14, 1982.

Very truly yours,

J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/LAE/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27
S/10

8204130104 820401
PDR ADOCK 05000458
S PDR