## LICENSEE EVENT REPORT

Elocitor.	EVENT HEROIT
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
	0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58
CON'T    0   1   REPORT   L   6   0   5   0   0   2   7   2     7   8   SOURCE   60   61   DOCKET NUMBER	68 69 EVENT DATE 74 75 REPORT DATE 80
O 2 On March 29, 1982, while performing	Surveillance Procedure SP(0)4.7.10.1.2.a, it
old was discovered that No. 2 Fire Pump	would not start in the automatic mode. No. 2
0 4   Fire Pump was declared inoperable a	at 1220 hours, and Action Statement 3.7.10.1
0 5 was entered.	
06	
07	
7 8 9 SYSTEM CAUSE CAUSE	COMP. VALVE
ODE SUBCODE 13 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	COMPONENT CODE PUMPXXX 18 SUBCODE V Z 16
17 LER RO EVENT YEAR REPORT NO. O 11 19	OCCURRENCE REPORT TYPE NO.
1 101 10 1 10 1 10	HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	0 0 0 Y (23) Y (24) N (25) W 0 7 0 (26)
	motor on No. 2 Fire Pump diesel engine had
[1] [ failed, preventing the engine from	starting. The voltage regulator and starter
were replaced, and the pump was sat	tisfactorily tested. At 2230 hours, April 2,
13   1982, No. 2 Fire Pump was declared	operable, and Action Statement 3.7.10.1 was
114 L terminated.	
FACILITY S POWER OTHER STATUS 30  1 5 G 28 0 0 0 29 N/A  1 10 12 13 44	METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT	LOCATION OF RELEASE 36
1 6 Z 33 Z 34 N/A  7 8 9 PERSONNEL EXPOSURES	N/A 45 80
1 7 0 0 0 37 Z 38 N/A	80
PERSONNEL INJURIES NUMBER O O O O O O NA NA	3 2
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A 82	05040105
PUBLICITY ISSUED DESCRIPTION 45	NRC USE ONLY
NAME OF PREPARER R. Frahm	68 69 80 5 PHONE: 609-935-0998