



**LOUISIANA
POWER & LIGHT**


142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 30, 1982

G. D. McLENDON
Senior Vice President

W3K-82-0255
Q-3-A35.07.40

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 40
Second Interim Report
"ITE-Gould Starter Coil Failure in Containment Cooling Fans"

Reference: 1) LP&L letter W3K-81-0412 to NRC dated November 17, 1981
2) Telecon - L. L. Bass (LP&L) to B. Crossman (NRC) on 4/27/82

Dear Mr. Collins:

In reference 1, LP&L committed to provide a final report on SCD #40 by April 30, 1982. Since the first interim report was submitted, the remaining six coils have been received and are now scheduled for installation during the first week of May.

Based on the above information, a final report will be submitted on or before May 31, 1982.

Very truly yours,

G. D. McLendon

GDMcL/LLB/grf

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



*IE 27
S/0*

8205070231 820430
PDR ADOCK 05000382
S PDR