(7.77)	RM 366 U. S. NUCLEAR REGULATORY COMMISSION	
	LICENSEE EVENT REPORT	
	CONTROL BLOCK	
	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	
	REPORT L 6 0 5 0 0 3 2 1 7 0 4 2 6 8 2 8 0 5 1 0 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80	
0 2	While searching a vehicle prior to its exiting the protected area, an	
03	unloaded .38 caliber revolver and a box of ammunition was discovered	
04	wrapped in a flannel rag under the driver's seat. There was no effect	
0 5	upon the public health and safety due to this non-repetitive event.	
0 6		
07		
10181		
7 8	9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE	
0 9	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	
10	$\begin{array}{c c c c c c c c c c c c c c c c c c c $	26)
	the adaptately appear the interior of the unbigle origin to the optimization of the	
	to adequately search the interior of the vehicle prior to its entry into	
12	the protected area. All security officers were briefed on searching	
13		
	the protected area. All security officers were briefed on searching	
7 .8	the protected area. All security officers were briefed on searching techniques.	
7 8 15 7 8	the protected area. All security officers were briefed on searching techniques.	
	the protected area. All security officers were briefed on searching techniques.	
	the protected area. All security officers were briefed on searching techniques.	
7 8 1 5 7 8 1 6 7 8 1 6 7 8 1 7 8 1 7 8 1 8	the protected area. All security officers were briefed on searching techniques.	
	the protected area. All security officers were briefed on searching techniques.	
7 8 1 5 7 8 1 6 7 8 1 6 7 8 1 7 8 1 7 8 1 8	techniques. techniques.	
7 8 1 5 7 8 1 6 7 8 1 6 7 8 1 7 8 1 7 8 1 7 8 1 7 8 1 7 8 1 9	the protected area. All security officers were briefed on searching techniques.	117-926

LER #: 50-321/1982-044 Licensee: Georgia Power Company Facility Name: Edwin I. Hatch Docket #: 50-321

Narrative Report for LER 50-321/1982-044

On 4/26/82 an unloaded .38 caliber revolver and a box of ammunition for this weapon was discovered under the driver's seat of a contractor's vehicle prior to its exiting the protected area. This resulted from a security officer failing to adequately search the interior of the vehicle prior to its entry into the protected area; however, the vehicle had been escorted to its destination inside the protected area by a security officer, the steering wheel disabled, the front doors locked and the keys retained by Security. The driver had authorized unescorted access to the protected area, but did not have access to the weapon while inside the protected area due to Security maintaining key to locked vehicle. The security officers were briefed on proper searching procedures on 4/27/82 and 4/28/82, and this briefing was formally documented. All officers that were not on duty are being briefed upon their return to duty. The contractor has been restricted from the plant site pending further investigation. This event was reported on Deviation Report 1-82-69.

This is a non-repetitive event, and there was no effect upon the public health and safety due to this event.