

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [G][A][E][I][H][1] [2][0][0]-[0][0][0][0][0][0]-[0][0] [3][4][1][1][1][1] [4] [] [5]

CON'T [0][1] [L] [6][0][5][0][0][0][3][2][1] [7][0][2][1][0][8][2] [8][0][2][2][5][8][2] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0][2] During normal power operation the 1C Plant Service Water Pump 1P41-C001C was taken
[0][3] out for pump seal repair at 0555 on 2-10-82 and the Tech. Specs. surveillance re-
[0][4] quirement per 4.5.J.2.b was not performed. This is a non-repetitive occurrence.
[0][5] There were no effects upon public health and safety due to this event.
[0][6]
[0][7]
[0][8]

[0][9] [W][A] [11] [A] [12] [A] [13] [Z][Z][Z][Z][Z][Z] [14] [Z] [15] [Z] [16]
[17] [8][2] [] [0][1][5] [] [0][3] [] [] [0]
[18][Z] [19][Z] [20][Z] [21][Z] [22][0][0][0][0] [23][Y] [24][N] [25][Z] [26][Z][9][9][9]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1][0] The missed surveillance requirement was an unintentional omission on the part of the
[1][1] licensed personnel on shift. Upon discovery of the missed surveillance at 1645 on
[1][2] 02-10-82, the required surveillance was started. The "C" PSW pump was returned to
[1][3] operable status at 1800 and the LCO was terminated.
[1][4]

[1][5] [F] [28] [0][6][8] [29] NA [30] [A] [31] Plant Personnel Observation [32]
[1][6] [Z] [33] [Z] [34] NA [35] NA [36]
[1][7] [0][0][0] [37] [Z] [38] NA [39]
[1][8] [0][0][0] [40] NA [41]
[1][9] [Z] [42] NA [43]
[2][0] [N] [44] NA [45]

GPO 1977-92

LER #: 50-321/1982-015
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1982-015

During normal power operation on 2-10-82 at 0555, the 1P41-C001C was tagged out to allow Maintenance to repair a seal leak on the Plant Service Water pump. Due to personnel error, the required immediate surveillance per Tech. Specs. 3.5.J.2.b was not performed. At 1615 on 2-10-82, it was discovered that the required surveillance was not performed. At 1645 the required surveillance was started on the A, B & D Plant Service Water pumps and was completed at 1700 on 2-10-82. The 1P41-C001C Plant Service Water pump was returned to operable status at 1800 on 2-10-82.

A revision to the LCO Status Sheet (HNP-901, Figure 1) has been submitted which will allow logging the required immediate action or surveillance to be performed and the subsequent action to be performed while LCO is in effect. Also, provisions were made to indicate the required date and time of the next surveillance. This change will allow the Shift Foreman and Shift Supervisor to determine if the required surveillance has been performed and the time and date of the next required surveillance.