

CONTROL BLOCK:

--	--	--	--	--	--	--

1

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE						30	CAT				58









REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

02 FIRE DOOR #517 WAS FOUND BLOCKED OPEN AND THE LATCH TAPED TO PREVENT

6 3 THE LATCH FROM WORKING. THIS CONSTITUTED AN INOPERABLE PENETRATION

0	4	FIRE BARRIER CONTRARY TO TECH. SPEC. 3.7.10. ACTION REQUIREMENTS
---	---	--

05 WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

17	REF/RO REPORT NUMBER	EVENT YEAR	REPORT NO.	CODE	TYPE	NO.
		8 2	0 2 6	0 3	L	0

ACTION TAKEN (H) (19) FUTURE ACTION (Z) (19) EFFECT ON PLANT (Z) (20) SHUTDOWN METHOD (Z) (21) HOURS (O) (O) (O) (O) (22) ATTACHMENT SUBMITTED (N) (23) NPRD-4 FORM SUB. (N) (24) PRIME COMP. SUPPLIER (A) (25) COMPONENT MANUFACTURER (X) (9) (9) (9) (26)

10 THE DOOR WAS REPORTED TO HAVE BEEN BLOCKED OPEN BY CONSTRUCTION

PERSONNEL FOR VENTILATION. UPON DISCOVERY, THE BLOCKAGE AND TAPE

WERE REMOVED AND THE DOOR MADE OPERABLE. THE CONTRACTOR SUPERVISORY

PERSONNEL WERE DIRECTED TO STRESS THE IMPORTANCE OF FIRE DOORS TO THE

14 | CRAFTSMEN UNDER THEIR SUPERVISION.

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
	F (20)	1 0 0 (30)	N/A	B (21) OA OBSERVATION	

PERSONNEL INJURIES

[illegible]

1 9 Z 42 N/A 8205250054 820518 80

ISSUED		DESCRIPTION		PDR		ADDCR		CSCC		S19		PDR	
2	0	N	44	N/A		S							

NAME OF PREPARER R.H. PIEHL

PHONE: (616) 465-5901

8205250054 820519
PDR ADDCK 05000315
S PDR

NRC USE ONLY

917-926