

Carolina Power & Light Company

82 MAY 2 A 9: 03

COAD 82-742

April 26, 1982

File: SH N-2/18 Item 75

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 101 Marietta Street, Northwest Atlanta, Georgia 30303

> SHEARON HARRIS NUCLEAR POWER PLANT DOCKET, NOS. 50-400, 50-401 SHOP WELD DEFICIENCIES ON JOSEPH OATES SUPPLIED HEAT EXCHANGERS

Dear Mr. O'Reilly:

On March 24, 1982, the NRC (Mr. C. Julian) was informed that the subject item was considered potentially reportable per the provisions of 10CFR50.55(e) and 10CFR21. The intent of this letter is to inform you that due to difficulties in gaining access for engineering examinations, due to sandblasting and painting operations, we have not been able to complete our reportability evaluation.

When access becomes available CP&L welding engineering personnel will continue to examine the remaining welds to determine the extent of these deficiencies. CP&L plant engineering personnel will then determine whether or not these deficiencies are reportable under the provisions of 10CFR50.55(e) and 10CFR21. It is anticipated that the investigation and evaluation of this problem will be completed by May 26, 1982, at which time the NRC will be informed of the results of our evaluation.

Completion of corrective action will depend on the results of the evaluation and extent of rework required. If this item is deemed reportable, the NRC will be so notified and the projected date of completion of corrective action provided through submittal of an interim letter.

8206010237

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602 OFFICIAL COPY

5110

T8,2

## Mr. J. P. O'Reilly

Thank you for your consideration in this matter.

Yours very truly,

N. J. Chiangi - Manager Engineering & Construction Quality Assurance/Quality Control

DR/mt

. .

9

cc: Mr. C. Maxwell Mr. V. Stello (2)