

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company  
Catawba 1 and 2

Docket Nos. 50-413 & 50-414  
License Nos. CPPR-116 & CPPR-117

As a result of the inspection conducted on February 26 - March 25, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V, as implemented by Topical Report Duke i-A, Section 17, paragraph 17.1.5 requires that activities affecting quality be prescribed by documented procedures appropriate to the circumstances.

Contrary to the above, an activity affecting quality was not prescribed by documented procedures on March 16, 1982 in that existing procedures did not preclude alteration of repair weld cavities after inspection had been performed. This resulted in alteration of a repair cavity for weld no. 1NC234-12 after inspection and rewelding without obtaining additional inspection.

This is a Severity Level IV Violation (Supplement II.E.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: APR 13 1982