

CONTROL BLOCK: | | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	1	7	0	3	0	9	8	2	3	0	4	0	8	8	2	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

0 2 | During normal operation while performing surveillance testing, 4 KV emer
0 3 | gency bus undervoltage relay 127-3 tripped conservatively high at 29.2 v
0 4 | olts. Technical Specification Table 3.2-8 requires a trip level setting
0 5 | of 24 +/- 4 volts. The undervoltage relay on the redundant 4 KV emergenc
0 6 | y bus was operating properly. There has been one previous similar occur
0 7 | rence (see RO 76-22).

08		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE						
0	8			E	B	11	E	12	A	13	R	E	L	A	Y	X	14	F	15	Z	16	
09		10		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.										
0	9			18	2	21	22	0	2	3	27	0	3	28	29	L	30	31	0	32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER						
E	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	A	25	G	0	8	10	25

10 Instrument drift was the cause of the event. Relay 127-3 was promptly re

11 calibrated and tested satisfactorily. Relay 127-3 is a General Electric

12 Type HGA relay. No further corrective action is planned.

FACILITY STATUS (1) 5 (28) F (29) NA OTHER STATUS (30) NA
 METHOD OF DISCOVERY (31) B Surveillance Test DISCOVERY DESCRIPTION (32) NA
 ACTIVITY CONTENT RELEASED OF RELEASE (33) Z (34) NA AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA
 PERSONNEL EXPOSURES NUMBER (37) 0 TYPE (38) Z DESCRIPTION (39) NA
 PERSONNEL INJURIES NUMBER (40) 0 DESCRIPTION (41) NA
 LOSS OF OR DAMAGE TO FACILITY TYPE (42) Z DESCRIPTION (43) NA
 PUBLICITY ISSUED (44) N DESCRIPTION (45) NA
 B204160133 B20408 PDR ADOCK 05000331 S PDR
 NRC USE ONLY

PHONE 319-851-5611