

01 | ALJMF1 | 700 - 00000000 - 00 | 341111 | 4 | 5

U | L | 05000348 | 7030582 | 8040282 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | At 1:00 on 3/05/82 the containment air lock was declared inoperable when the cam lock

03 | on the outer door was found broken. Tech. Spec. 3.6.1.3 requires this air lock to be

04 | operable. Tech. Spec. 3.6.1.3 action statement requirements were met. Health/safety

05 | of the public was not affected.

09 | SA | E | B | PENETR | A | Z

17 | 82 | - | 011 | - | 03 | L | - | 0

AZ | Z | Z | 0000 | N | N | A | C310

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | This event was caused by a broken cam lock. The broken cam lock on the outer door was

11 | repaired. Following the satisfactory completion of FNP-0-STP-607.0 (Containment

12 | Airlocks Interlock Test) the containment airlock was declared operable at 2300 on

13 | 3/05/82.

15 | C | 000 | NA | A | Operational Event

16 | Z | Z | NA | NA

17 | 000 | Z | NA

18 | 000 | NA

19 | Z | NA

20 | N | NA