

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|---|---|---|---|----------------|---|---|---|---|---|---|---|---|---|-----------------|---|---|---|---|---|--|---|--|--|-----------|--|--|--|--|--|--|--|--|--|
| 0 | 1 | N | J | S | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5 | | | | | | | | | | | | |
| 7 | 8 | LICENSEE CODE | | | | | | | | | | LICENSE NUMBER | | | | | | | | | | LICENSE TYPE JO | | | | | | | | | | 57 CAT 58 | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|---|---|---|---|---------------|---|---|---|---|---|---|---|---|---|------------|---|---|---|---|--|--|--|--|--|-------------|--|--|--|--|--|--|--|--|--|
| 0 | 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 0 | 4 | 2 | 5 | 8 | 2 | 8 | 0 | 5 | 2 | 1 | 8 | 2 | 9 | | | | | | | | | | | | | | | |
| 7 | 8 | REPORT SOURCE | | | | | | | | | | DOCKET NUMBER | | | | | | | | | | EVENT DATE | | | | | | | | | | REPORT DATE | | | | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On April 25, 1982, during routine operation, the Control Room Operator noticed that both channels of Refueling Water Storage Tank (RWST) level indication showed that the tank contained less than the minimum volume required by the Technical Specification. At 1600 hours, the RWST was declared inoperable, and Action Statement 3.5.5 was entered. This occurrence constituted operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b. (82-020, 81-24)

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------|---|--------------|---|---------------|---|-----------------|---|-----------------|---|-------|---|----------------------|---|------------------|---|----------------------|---|------------------------|---|-----------------|---|-------------|---|--------------|---|---|
| 0 | 9 | S | F | A | B | A | C | C | U | M | U | Z | Z | 8 | 2 | 0 | 2 | 8 | 0 | 3 | L | 0 | W | 1 | 2 | 0 |
| 7 | 8 | SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | COMP. SUBCODE | | VALVE SUBCODE | | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | | |
| LER NO REPORT NUMBER | | ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | | | | | | | | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The RWST contained volume was inadvertently decreased below the specification limit while refilling the Spent Fuel Pool. Makeup to the RWST was initiated, and at 1729 hours, the contained volume was within specification. The RWST was declared operable, and Action Statement 3.5.5 was terminated. The operator involved was counseled by the Senior Shift Supervisor concerning Technical Specification 3.5.5.

| | | | | | | | | | |
|-------------------------------|---|---------------------|---|--------------------|---|---------------------|---|-----------------------|--|
| 1 | 5 | E | 0 | 6 | 2 | N/A | A | Operator Observation | |
| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | |
| ACTIVITY CONTENT | | RELEASED OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | | | |
| PERSONNEL EXPOSURES | | NUMBER | | TYPE | | DESCRIPTION | | | |
| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | | | | | |
| LOSS OF OR DAMAGE TO FACILITY | | TYPE | | DESCRIPTION | | | | | |
| PUBLICITY | | ISSUED | | DESCRIPTION | | | | | |

NAME OF PREPARER R. FrahmPHONE: (609) 541-5900 6298206110047 820601
PDR ADOCK 05000272
S PDR