

**Detroit
Edison**

Donald A. Wells
Manager Quality Assurance
(313) 237-9657

2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

50-41
May 21, 1982
EF2-58068

Mr. James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) on Defects in Eberline
Instrument Corporation Radiation Monitoring Equipment (#67)


Dear Mr. Keppler:

On April 23, 1982, Detroit Edison's Mr. H.A. Walker, Supervisor-Construction Quality Assurance, telephoned Mr. H. Wescott of NRC Region III, to report on a problem with defects in Eberline Instrument Corporation Radiation Monitoring Equipment at the Fermi 2 site.

This item deals with defects in Eberline Instrument Corporation's radiation monitoring equipment which had been supplied to the Fermi 2 site. A letter was received from the NRC site resident inspector documenting a 10CFR21 report on the Eberline Instrument problem. Although the letter indicates Detroit Edison was notified of the problem by Eberline, we have not been able to locate the report or the letter. Detroit Edison has verified that the affected equipment was received, and was in use at the Fermi site.

Another report on this item, either interim or final, is scheduled to be sent to you on or before September 17, 1982. If you have questions concerning this matter, please contact Mr. H.A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,



DAW/HAW/cp

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166

8206150333 820521
PDR ADOCK 05000341
S PDR

JUN 9 1982

JE19