

USNRC REGION
ATLANTA, GEORGIA

32 JUN 14 1982

Alabama Power
the southern electric system

P. O. Drawer 470
Ashford, AL 36312
June 10, 1982
FNP-82-0523

50-348

Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
101 Marietta Street, N.W.
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

This is to confirm the telephone call to Mr. V. Brownlee (NRC) at approximately 1512 on June 10, 1982, by Mr. J. D. Woodard (APCo).

On June 9, 1982, it was determined that a service water valve mislabeling error could have led to a condition potentially reportable under Unit 2 Tech. Spec. 6.9.1.12 i. Certain A & B train service water cooling valves associated with the 2B charging pump were mislabeled i.e., "A" train marked as "B" and vice versa. As a result it is possible that the Limiting Condition for Operation for the charging pump was not satisfied during certain time periods in plant life.

Immediately upon discovery of the condition, the valves were correctly relabeled. Similar valves in Units 1 and 2 were verified as being correctly labeled.

An investigation is continuing and further details will be provided in the followup report.

Yours truly,


W.G. Hairston, III
Plant Manager

Joseph M. Farley Nuclear Plant

WGH/HMM:sjb

CC: H. O. Thrash
D. N. Morey
W. G. Ware
Document Control

8206210464 820610
PDR ADOCK 05000348
S PDR

COPIES

IE 22