

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC 2200-000000-000341111145  
7 8 9 14 15 25 26 37 38 39 40

CON'T  
01 REPORT SOURCE L6050000316705208230617829  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING NORMAL OPERATIONS, THE WEST CENTRIFUGAL CHARGING PUMP WAS REMOVED FROM  
03 SERVICE TO REPAIR A LEAKING 1/2" THREADED SEAL WATER LINE ELBOW AT THE INBOARD  
04 MECHANICAL SEAL HEAT EXCHANGER. THIS CONSTITUTED AN INOPERABLE CHARGING PUMP,  
05 CONTRARY TO T.S. 3.1.2.4. THE EAST PUMP REMAINED IN SERVICE AND ACTION REQUIREMENTS  
06 WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

03 \_\_\_\_\_

03 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
P C X Z P I P E X X A Z  
9 10 11 12 13 18 19 20

17 LER RO REPORT NUMBER 82  
EVENT YEAR 82  
SEQUENTIAL REPORT NO. 046  
OCCURRENCE CODE 03  
REPORT TYPE L  
REVISION NO. 0

ACTION TAKEN B18 Z19  
FUTURE ACTION Z20  
EFFECT ON PLANT Z20  
SHUTDOWN METHOD Z21  
HOURS 0000  
ATTACHMENT SUBMITTED N23  
NPRO-4 FORM SUB. N24  
PRIME COMP. SUPPLIER N25  
COMPONENT MANUFACTURER C68526

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE CAUSE OF THE LEAK COULD NOT BE DETERMINED. THE FITTING WAS REMOVED, THREADS  
11 CLEANED, FITTING REPLACED AND PUMP RETURNED TO SERVICE IN 6 HOURS AND 39 MINUTES.  
12 AS A PRECAUTIONARY MEASURE, THE EVENT HAS BEEN DISCUSSED WITH PERSONNEL INVOLVED.

14 \_\_\_\_\_

15 FACILITY STATUS E28  
% POWER 10029  
OTHER STATUS NA  
METHOD OF DISCOVERY B31  
DISCOVERY DESCRIPTION OPERATOR OBSERVATION

15 RELEASED OF RELEASE Z33 Z34  
AMOUNT OF ACTIVITY NA  
LOCATION OF RELEASE NA

17 PERSONNEL EXPOSURES NUMBER 00037  
TYPE Z38  
DESCRIPTION NA

17 PERSONNEL INJURIES NUMBER 00040  
DESCRIPTION NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z42  
DESCRIPTION NA

20 PUBLICITY ISSUED DESCRIPTION N44  
8206240335 820617  
PDR ADOCK 05000316  
S PDR

NAME OF PREPARER R.H. PIEHL

PHONE 616-465-5901