




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 17, 1982

G. D. McLENDON
Senior Vice President
W3K82-0352
Q-3-A35.07.37

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Interim Status Report of Significant Construction Deficiency No. 37
"Temperature Detectors (RTD's) Failure"
Third Interim Report

Reference: 1) LP&L Letter W3K82-0193 to USNRC April 1, 1982
2) Telecon - L. Martin (NRC) to I (LP&L) on June 16, 1982

Dear Mr. Collins:

The above referenced Interim Report on Significant Construction Deficiency No. 37 committed to a Final Report by June 15, 1982.

This problem has been addressed by DCN-NY-IC-654. The manufacturer has given notice of a shipping date late in June 82 for replacement/repair of equipment. LP&L respectfully requests an extension date for the submittal of the Final Report until August 6, 1982.

Very truly yours,

G. D. McLendon

GDMcL/LLB/ncd

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27