NRC FOR	
(7-77) •,	LICENSEE EVENT REPORT Update Report: Previous Report Date 5-11-82
	CONTROL BLOCK:
01 78	$ \underbrace{\left[\begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T	REPORT L 6 0 5 0 - 0 3 2 4 0 0 4 1 6 8 2 8 0 6 2 9 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During plant operation, post-accident monitoring Control Room recorder/indicator,
03	2-CAC-AR-1263, was observed exhibiting downscale indications of drywell oxygen con-
0 4	centration. At the time of this discovery the redundant Control Room instrument,
0 5	2-CAC-AR-1259, exhibited a normally expected drywell oxygen concentration. This
06	event did not affect the health and safety of the public.
0 7	
018	Technical Specification 3.3.5.3, 3.6.6.4, 6.9.1.9b
0 9 7 8	$\begin{array}{c} \begin{array}{c} \text{SYSTEM} \\ \text{CODE} \end{array} \\ \begin{array}{c} \text{CAUSE} \\ \text{CODE} \end{array} \\ \begin{array}{c} \text{CAUSE} \\ \text{SUBCODE} \end{array} \\ \begin{array}{c} \text{COMPONENT CODE} \\ \text{SUBCODE} \end{array} \\ \begin{array}{c} \text{COMPONENT CODE} \\ \text{SUBCODE} \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \end{array} \\ \end{array} $ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \end{array} \\ \end{array} \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \end{array} \\ \end{array} \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \end{array} \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \\ \end{array} \\ \\ \end{array} \\ \\ \begin{array}{c} \text{SUBCODE} \\ \text{SUBCODE} \end{array} \\ \\ \\ \\ \end{array} \\ \\ \\ \end{array} \\ \\ \\ \end{array} \\ \\ \\ \\
	Image: Number Num Number Number Number Number Number Number Number Num
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER A (B) Z (9) Z (20) Z (21) 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
10	The downscale 1263 indications occurred because the instrument slide wire contactor
11	was slightly bent, attributed to component wear. As a result the contactor was
12	making poor contact with the slide wire. The contactor was replaced, adjusted, and
13	returned to service. As the contactor failure is attributed to component wear, no
1 4 7 8	further action to this event is required.
15	PACILITY STATUS STAT
	ACTIVITY CONTENT RELEASE AMOUNT OF ACTIVITY 35 2 33 2 34 10 NA 44 45 LOCATION OF RELEASE 36 NA 45 80
	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8	9 11 12 13 REFECTIVELING 11 13 80
1 R 7 8	NUMBER 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
19	
20 7 B	PUBLIC 8207090250 820629 NRC USE ONLY ISSUED PDR NA IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	NAME OF PREPARER M. J. Pastva PHONE: 919-457-9521