Entergy Operations, Inc.

Kilona: LA 70086 Tel 504 739 6774

R. F. Burski Orector Neciliar Kniety Webstere 3

W3F1-93-0367 A4.05 PR

December 3, 1993

ENTERGY

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Subject: Waterford 3 SES Docket No. 50-382 License No. NPF-38 NRC Inspection Report 93-31 Reply to Notice of Violation

Gentlemen:

In accordance with 10CFR2.201, Entergy Operations, Inc. hereby submits in Attachment 1 the response to the violation identified in Appendix A of the subject Inspection Report.

If you have any questions concerning this response, please contact T.S. Becker at (504) 739-6693.

Very truly yours,

080009

R.F. Bunski

R.F. Burski Director Nuclear Safety

9312100289 931203

ADOCK 05000382

PDR

RFB/TSB/ssf Attachment

:00

PDR

J.L. Milhoan (NRC Region IV), D.L. Wigginton (NRC-NRR), R.B. McGehee, N.S. Reynolds, NRC Resident Inspectors Office

Attachment to W3F1-93-0367 Page 1 of 2

## ATTACHMENT 1

# ENTERGY OPERATIONS. INC. RESPONSE TO THE VIOLATION IDENTIFIED IN APPENDIX A OF INSPECTION REPORT 93-31

## VIOLATION NO. 9331-01

e, ich

License Condition E of the Waterford Steam Electric Station, Unit 3, Operating License NPF-38, dated March 16, 1985, requires that the licensee fully implement and maintain in effect the Commission approved Physical Security Plan, including amendments and changes made pursuant to the authority of 10 CRF 50.54 (p).

Paragraph 5.6.1.3 of the Physical Security Plan requires, in part, that prior to entering the protected area, hand-carried packages are inspected by visual means or through the use of X-ray package examination equipment.

Paragraph 5.3.9.1 of Security Procedure PS-011-102, Revision 13, "Personnel Access and Exit," dated September 28, 1992, requires, in part, that prior to entering the protected area the individual's hand-carried items should be placed on the conveyor belt for purposes of having them searched by means of the package X-ray examination device. Items that are too large or otherwise cannot be searched by the X-ray examination device shall be physically searched by security personnel.

Contrary to the above, the inspector determined by observation on October 14, 1993, that a hand-carried item entered the protected area without being searched by the X-ray examination device or being physically searched by a security officer.

### RESPONSE

#### (1) Reason for the Violation

Entergy Operation, Inc. admits this violation and believes that the root cause is personnel error in that the required procedure was not followed. PS-011-102 requires that hand-carried items be searched prior to entering the protected area. However, a Security Officer assigned to search duties (Personnel Search Officer) failed to search a coffee cup that was passed around the portal metal detector. The officer was distracted by another individual and did not notice a Waterford 3 badged employee place the coffee cup on the inspection tray beside the metal detector. The employee walked through the detector, picked up the cup, and proceded through the explosives

Attachment to W3F1-93-0367 Page 2 of 2

detector, after which, the employee entered the protected area without having the coffee cup searched. During this time the Personnel Search Officer became involved with other employees entering the metal detector and failed to notice the coffee cup being taken into the protected area.

# (2) Corrective Steps That Have Been Taken and the Results Achieved

The Security Officer involved in the incident was suspended in accordance with the Contractor Security Disciplinary Standards. Additionally, the Officer was debriefed in accordance with the Improving Human Performance program.

## (3) Corrective Steps Which Will Be Taken to Avoid Further Violations

This incident appears to be an isolated case of an inadequate search. However, in an effort to prevent recurrence and heighten the awareness of this incident, Security force personnel were given refresher training on the processing of personnel through the Primary Access Point.

# (4) Date When Full Compliance Will Be Achieved

1. 10 8

Waterford 3 was in full compliance on October 27, 1993.