July 23, 1982

File: SH N-2/18 Item 91 2 JUL 2 A8: 31 CQAD 82-1275

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 101 Marietta Street, Northwest Atlanta, Georgia

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1

DOCKET NO. 50-400

DEFICIENCIES IN WELDED STUDS ON EMBEDDED STRIP PLATES

Dear Mr. O'Reilly:

Attached is the cover sheet for the final 10CFR50.55(e) report on the subject deficiency. Please replace the cover sheet with "INTERIM REPORT" on it that was inadvertantly transmitted to you via our CQAD 82-1249 letter dated July 19, 1982, with the attached cover sheet.

If you have any questions regarding this matter, please do not hesitate to contact me.


Yours very truly,

NJC/mt Attachment

cc: Mr. G. Maxwell W/A Mr. V. Stello (2) W/A

N. J. Chiangi - Manager Engineering & Construction Quality Assurance/Quality Control

8208050202 820723 PDR ADDCK 05000400 S PDR ---



CAROLINA POWER & LIGHT COMPANY SHEARON HARRIS NUCLEAR POWER PLANT

UNITS NO. 1 AND 2

DEFICIENCIES IN WELDED STUDS ON EMBEDDED STRIP PLATES - ITEM 91

FINAL REPORT July 16, 1982

Reportable Under 10CFR50.55(e)