

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK fields: 1, 2, 3, 4, 5

CON'T fields: 6, 7, 8, 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 INTERIM REPORT: During normal operation, while conducting surveillance
0 3 required by TS Table 4.2-5, the Drywell Equipment Drain Sump Flow Inte-
0 4 grator was found out of calibration approximately 4.5 percent and could
0 5 not be adjusted to within tolerance. No significant hazard existed.

SYSTEM CODE, CAUSE CODE, COMPONENT CODE, LER/RO REPORT NUMBER, ACTION TAKEN, EFFECT ON PLANT, SHUTDOWN METHOD, HOURS, ATTACHMENT SUBMITTED, NPRO-4 FORM SUB., PRIME COMP. SUPPLIER, COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 The reason for inability to adjust the integrator has not been determined.
1 1 The entire assembly was replaced with a spare, calibration was performed
1 2 and the instrument was returned to service later the same day. A follow-
1 3 up report will provide additional information.

FACILITY STATUS, % POWER, OTHER STATUS, METHOD OF DISCOVERY, DISCOVERY DESCRIPTION, ACTIVITY CONTENT, PERSONNEL EXPOSURES, PERSONNEL INJURIES, LOSS OF OR DAMAGE TO FACILITY, PUBLICITY