	SAFETY I	NSPECTION		
	a an an an an a de anna a dheann ann an			
CTL ENGINEERING, INC. 2860 FISHER ROAD COLUMBUS, OHIO 43204		2. REGIONAL OFFICE U. S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137		
DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTIO	N
030-05758	34-08331	-01	OCTOBER 15	5, 1990
of a B. Containers located in labeled to indicate the presence C frequencies. 10 CFR D. Records of 10 CFR	personnel, and observations by the no violation is were observed. You have taken to correct the violat ur activities, as checked below, were DN which is required to be posted in	inspector. The findings tions identified during th in violation of NRC req accordance with 10 CFF .203(f)(1), or (f)(2). License ( or License Condition N	as a result of this inspection a le last inspection. We have no uirements. R 19.11. 	are as follows: b further questions on to indicate the presence b), (c), (d), (e) or 34.42 were not propert
			were	not made in accordan
			umber	
H				
J				
<u>к</u>				
I however a series at an initial in "If share also and	tions described by me to the inspect		of the violations identified in to further response will be suf	