License: 42-26928-01 Docket: 30-30429/90-01

ProTechnics International, Inc. ATTN: John W. Chisholm, President 14760 Memorial Drive

Suite 206

Houston, Texas 77079

Gentlemen:

Thank you for your letter of October 12, 1990, in response to our request for further information to supplement your previous reply to the Notice of Violation issued to ProTechnics International, Inc., on June 7, 1990. We have reviewed your reply and find it responsive to the concerns raised in the Notice. We will review the implementation of your corrective actions during a future inspection to determine whether full compliance has been achieved and will be maintained.

Original Signed By:

A: B. BEACH

A. Bill Beach, Director Division of Radiation Safety and Safeguards

cc: Texas Radiation Control Program Di ector

bcc w/copy of licensee letter:
DMB - Original (IE-07)
RDMartin
ABBeach
LAYandell
MRodriguez, OC/LFDCB (MS 4503)
CLCain
WLFisher
LLKasner
NMSIS
MIS System
RIV Files (2)
RSTS Operator

RIV:NMSIS/V LLKasner/ch //2/90 C:NMSISUKC CLCain 11/5/90 D: DRSS ABBOOCH 11 /6 /90

9011130366 901107 REG4 LIC30 42-26928-01 PDC 26 m



CCT 19 Well

October 12, 1990

Mr. Bill Beach U.S. Nuclear Regulatory Commission Region IV Nuclear Materials Safety Section 611 Ryan Plaza Drive. Suite 1000 Arlington, TX 75011

Re: License : 42-26928-01 Docket : 30-30429/90-01

Dear Mr. Beach:

This is a correction for our letter dated June 20, 1990 which was a response to your notice of violation dated June 7, 1990. The previous response did not address each of the four items specified in the notice of violation.

- Item 1) Reason for occurrence: Safety training was not thorough enough to answer all questions regarding removable contamination surveys and the requirement of the survey.
- Item 2) Corrective steps taken include changing the units of measure from dpm to μ Ci per 100 cm² on documents used to record receipt of radioactive materials, as outlined in 10 CFR 20.205 (b)(1).
- Item 3) Corrective steps to prevent reoccurrence: All licensed personnel have had a review of 10 CFR 20.205 (a-d) and the procedures for receiving radioactive materials, as outlined in the operating and emergency procedures manual provided by ProTechnic International, Inc.

IC 92-305 XP8

TEOT

Item 4) These corrective measure have been implemented as of June 20, 1990.

Sincerely,

Doug Elliott Deputy Radiation Safety Officer

DE/bmw

cc: District Manager All Supervisors

[f:de/nrc4]