

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION.)

W 11111111 11111111 11111111

010501-10140130 0101210720 0101110718

FOLLOWING FALSE ALARMS OF ZONE 13 FIRE AND SMOKE DETECTION SYSTEM, IT WAS PLACED IN "BYPASS" TO DISABLE ALARM FUNCTION. FIRE WATCH PATROL WAS NOT PROMPTLY INITIATED. AUTOMATIC FIRE PROTECTION OF ZONE 13 WAS NOT IMPAIRED. TECHNICAL SPECIFICATION 4.2.17.1 REQUIRES THE INITIATION OF A ONCE PER HOUR INSPECTION AT THE AREA IN WHICH FIRE PROTECTION INSTRUMENTATION HAS BEEN AFFECTED.

SYSTEM CODE: A B  ZONE CODE: A  S. CODE: A  COMPONENT CODE: Z Z Z Z Z  (14)  TYP. SUBCODE: Z  (15)  VALUE CODE: Z  (16)

EFFECT YEAR: 7 8  23  0 0 8  PRACTICE CODE: 0 3  REPORT TYPE: L  1  REVISION NO:

EFFECT DATE: X Z  Z  Z  Z  0 0 0 0  ATTACHMENT SUBMITTED: Y  APPROX FORM. SUB: M  (14) PRIME COMP. SUPPLIER: Z  (25) COMPONENT MANUFACTURER: 7 9 9 9  (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)

ONE OF THREE ZONE 13 DETECTOR HEADS MALFUNCTIONED. HEAD WAS REPAIRED, TESTED AND RETURNED TO SERVICE WITHIN APPROXIMATELY SEVEN HOURS. APPLICABLE PATROL REQUIREMENTS OF RECENTLY IMPLEMENTED TECHNICAL SPECIFICATIONS WERE OVERLOOKED BY OPERATING STAFF. THE OPERATING STAFF WAS REMINDED OF THIS SPECIFIC REQUIREMENT AND OTHER RELATED ACTIONS RECENTLY IMPOSED.

OTHER EXTENSION: NA  TESTED BY: C  MANUFACTURER DESCRIPTION:

Z Z  NA  NA

0 0 0  Z  NA

0 0 0  NA

Z  NA

NA

7812110167

R. F. Shinsak

618-680-2331