

Appendix

NOTICE OF VIOLATION

Neyer, Tiseo and Hindo, Ltd.

License No. 21-14894-01

As a result of the inspection conducted on June 24, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 17 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in application dated September 23, 1981. This application states that gauges shall be fully secured within any transportation vehicle away from the passengers compartment and when transported, are installed in the standard Troxler storage and shipping containers.

Contrary to this requirement, it was learned through statements of licensee representatives that gauges have been transported unfastened inside the vehicle cab.

This is a Severity Level IV violation (Supplement VI).

Actions have been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

8/4/82  
Dated

J. R. Miller  
J. R. Miller, Chief  
Technical Inspection Branch