12-81) 0 CFR 2-201	SAFETY INS	PECTION	30-6857
	SALLITING	CONTON	20-0-0-
LICENSEE	2.	REGIONAL OFFICE	
Department of the Navy Naval Submarine Base Repair Department 705 Pearl Harbor, HI 96860		U.S. NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE, SUITE 210 WALNUT CREEK, CA 94596	
DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
	53-10226-01		July 1, 1982
ensee.			
representative records, interviews, with personn 1. Within the scope of this inspection, no violat	ns and the conditions of your li nel, and observations by the ins ions were observed.	icense. The inspection pector. The findings a	consisted of selective examinations of procedures
3. During this inspection certain of your activit THIS IS A NOTICE OF VIOLATION which			
Aof a			was not properly posted to indicate the present . 10 CFR 20.203(b), (c), (d), (e) or 34.4.
0.0			
frequencies. 10 CFR		License Co	of sealed sources were not performed at the prop andition Number
D. Records of	or l	icense Condition Nur	were not properly maintained
E. Documents were not properly posted or	otherwise made available. 10 C	FR 19.11.	
F. Reports or notifications of			were not made in accordance
	or L		nber
Тн.			7
-			
		L. A. C. Mark	
J			
J			
Is statement of corrective actions is made in acco e NRC. 8208130074 820716	ibed by me to the inspector will prodence with the requirements o	of 10 CFR 2.201. No f	he violations identified in the items checked above urther response will be submitted unless required i
his statement of corrective actions is made in acco e NRC.	ibed by me to the inspector will protence with the requirements o	the taken to correct to of 10 CFR 2.201. No f	he violations identified in the items checked above urther response will be submitted unless required in DARM 17/16/82