



LER 82-021

August 6, 1982

ATTACHMENT 1

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

This is an update to the telegram sent because of conservative action taken, based upon the measurement we had at that time. A temporary change was made to fix the position of the containment fan coil unit dampers. However, further measurements have demonstrated that all four containment fan coil units will operate in accordance with their design requirements. The low flow measurements were a result of fan interactions between the two fans feeding the common containment ring - header duct work. Investigation of this event is continuing.