SAFEGUARDS INFORMATION



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W., SUITE 2900 ATLANTA, GEORGIA 30323-0199

Report Nos. 50-327/93-51 and 50-328/93-51

Licensee: Tennessee Valley Authority

6N 38A Lookout Place 1101 Market Street

Chattanooga, TN 37402-2801

Docket Nos. 50-327 and 50-328

License Nos. DPR-77 and DPR-79

Facility Name: Sequoyah 1 and 2

Inspection Conducted: November 15-19, 1993

A. Tillman, Safeguards Inspector

Accompanying Personnel: D. Thompson, Safeguards Inspector

Approved by: ADJA A. A. A. D. McGuire, Chief Safeguards Section

PDR

Nuclear Materials Safety and Safeguards Branch

Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, announced inspection was conducted in the areas of Physical Security Program for Power Reactors, specifically: Management Support, Security Program Plans and Implementing Procedures, and Security Program Audit; Physical Barriers, Protected and Vital areas; Access Control -Personnel, Packages and Vehicles; Compensatory Measures and Communications. In addition, the status of the licensee's programmed upgrade of physical security systems and facilities was reviewed.

Results:

In the areas inspected, one apparent violation relating to six licensee identified events of failure to comply with procedural requirements for access control was confirmed. Review and observation of routine security operational activities during the course of the inspection verified that the licensee was in compliance with regulatory requirements and commitments of the approved Physical Security Plan with the exception of the failure to comply with procedural requirements as noted above. The Security Force was adequately staffed and demonstrated an acceptable level of job knowledge and performance capability. Further review confirmed continued progress in the installation 9312220016 931215
PDR ADDCK 05000327

SAFEGUARDS INFORMATION Enclasures this document is decontrolled

SAFEGUARDS INFORMATION

2

and implementation of the security system upgrade. However, the scheduled completion date of October 30, 1993, had been exceeded and a new schedule for completion of the system upgrade had not been established, due in part to identification of deficiencies in the security system computer software. Testing by licensee technicians to resolve the deficiencies was observed by the inspectors.

SAFEGUARDS INFORMATION

Document transmitted berewith contains sensitive unclassified information. When separated from enclosures, this document is decorateled.