

APPENDIX A

AIRCO Welding Products
Docket No. 99900774/82-01

NOTICE OF VIOLATION

As a result of the inspection conducted on May 17-21, 1982, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.21 of 10 CFR Part 21, dated December 18, 1981, states in part:
"(a) Each individual, corporation, partnership or other entity subject to the regulations in this part shall adopt appropriate procedures to: (1) provide for; (i) evaluating deviations; or (ii) informing the licensee or purchaser of the deviation in order that the licensee or purchaser may cause the deviation to be evaluated unless the deviation has been corrected"

Contrary to the above, documentation was not made available to the NRC inspector to verify the existence of procedures to evaluate deviations or inform the licensee or purchaser of the deviation.

This is a Severity Level V Violation (Supplement VII).