

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C A I S O S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5

CON'T 01 REPORT SOURCE L 0 5 0 0 0 3 6 1 7 0 7 1 5 8 2 8 0 8 1 3 8 2 9

02 While in Mode 3, the condensate storage tank T-121 water level fell below
03 the Technical Specification 3.7.1.3 limit on 4 occasions. There was no
04 consequence to the public health and safety since there was no significant
05 decay heat in the core.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

10 Inadequate makeup water control to tank T-121 and a more restrictive than
11 necessary Technical Specification limit were the cause. Corrective actions include
12 a proposed Technical Specification change and a design change to install automatic
13 level control prior to 100% power operation.

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
18 PERSONNEL INJURIES NUMBER DESCRIPTION

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
20 PUBLICITY ISSUED DESCRIPTION

8208200204 820813 PDR AD0CK 05000361 S PDR
NAME OF PREPARED H.B. RAY PHONE 714-492-7700