

SAFEGUARDS INFORMATION

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports Nos. 50-10/93005(DRSS); 50-237/93033(DRSS); 50-249/93033(DRSS)

Dockets No. 50-10; 50-237; 50-249

License Nos. DPR-02; DPR-19; DPR-25

Licensee: Commonwealth Edison Company
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Facility Name: Dresden Nuclear Power Station, Units 1, 2, and 3

Inspection Conducted: December 6-8 and 14-16, 1993

Date of Previous Routine Physical Security Inspection: June 7 - 10, 1993

Type of Inspection: Announced Routine Physical Security

Inspector: T. J. Madeda
T. J. Madeda
Physical Security Inspector

1/3/94
Date

Approved By: James R. Creed
James R. Creed, Chief
Safeguards & IRC Section

1/4/94
Date

Inspection Summary

Inspection on December 6-8 and 14-16, 1993 (Report Nos. 50-10/93005(DRSS); 50-237/93033(DRSS); 50-249/93033(DRSS))

Areas Inspected: Routine, announced physical security inspection involving: Management Support, Security Program Plans and Audits; Protected and Vital Area Physical Barriers, Detection and Assessment Aids; Protected Area Access Control of Personnel and Packages; and Followup on Previous Inspection Findings.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined. However, three weaknesses in the security program were identified regarding: (1) quality of search of some hand-carried items, (2) quality of personnel search and (3) an explosive detector vulnerability.

Inspection results showed that the security program was being implemented and managed in an effective manner, three weaknesses were identified in the area of ingress screening activities. When identified, good corrective action was taken for each finding. Observation and review of documentation showed an

SAFEGUARDS INFORMATION

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

9401120017 940105
PDR ADOCK 05000010
PDR
Q

SAFEGUARDS INFORMATION

effective level of performance relating to security barrier integrity and intrusion detection capability. Review of audit programs showed a good level of involvement in independent and self audit activities. Performance of assessment equipment was very good. Overall, security performance during this inspection was good.