LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK:
0 1 M A Y K R 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 6 CAT 58
CON'T SOURCE L 6 0 5 0 0 0 0 2 9 7 0 7 1 3 8 2 8 0 8 1 2 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During normal full power operation, SI MOV-1 motor operator contactor ci
[0]3 [rcuit control transformer primary winding grounded. The motor operator w]
[0]4] as disabled for 7 minutes for replacement of the control transformer (T.)
[0] [S.3.5.1.f). A dedicated operator was placed on station to operate SI-MOV]
[0] 6] 1 if needed. This event caused no adverse effect on the health and safe
0 7 ty of the public.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LER/RO REPORT NUMBER 2 23 23 24 26 27 28 29 30 31 30 32 ATTACHMENT FORM SUB. PRIME COMPONENT MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER LA 18 Z 19 Z 20 Z 21 Z 21 Z 20 Z 21 Z 20 Z 20 Z 20
This event was caused when nearby construction activity resulted in rain
water entering EMCC-2 and SI-MOV-1 operator circuit contactor, groundij
ing the control transformer. The transformer (type W Westinghouse MCC-SO
1 3 [#BSC-51494-1 Starter #CG51J086) was replaced in kind. The openings have
been permanently sealed. No further actions necessary.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E (28) 1 0 0 (29) NA A (31) Operator Observation
7 8 9 10 12 13 44 45 46 46 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) 1 6 Z 33 Z 34 NA
1 7 NUMBER OF TYPE DESCRIPTION (39) 7 8 9 11 12 13 NA 80
PERSONNEL INJUHIES NUMBER DESCRIPTION 41 NA
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY 43 PDR ADDCK 05000029 7 8 9 10 NA S PDR ADDCK 05000029 80
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA
7 8 9 10 68 69 80.5 NAME OF BREBARER Donald A. Rice PHONE (413) 625-6140