

APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

Inspection Report: 50-498/94-03
50-499/94-03

Operating Licenses: NPF-76
NPF-80

Licensee: Houston Lighting and Power Company
P.O. Box 1700
Houston, Texas 77251

Facility Name: South Texas Project

Inspection At: Bay City, Texas

Inspection Conducted: January 11-14, 1994

Inspector: M. D. Schuster, Senior Physical Security Specialist

Approved:

Blaine Murray
Blaine Murray, Chief, Facilities Inspection
Programs Section

1/21/94
Date

Inspection Summary

Areas Inspected (Units 1 and 2): Routine, announced inspection of the physical security program for power reactors including assessment aids, testing and maintenance, and compensatory measures.

Results:

- Alarm Stations and communications were properly implemented. Improvements were noted in the radio system (Section 1.1).
- Isolation Zones were properly maintained (Section 1.2).

- Problems continue to exist with the quality of the video cameras and monitors. Initiatives have been approved to upgrade and correct these problems (Sections 1.3 and 2.1).

Summary of Inspection Findings:

- Inspection Followup Item 498/9403-01; 499/9403-01 was opened (Section 1.3).
- Inspection Followup Item 498/9132-01; 499/9132-01 was closed (Section 2.1)
- Inspection Followup Item 498/9132-02; 499/9132-02 was closed (Section 2.2)
- Inspection Followup Items 498/9234-03, 498/9323-01; 499/9234-03, 499/9323-01 were closed (Section 2.3)

Attachment:

- Persons Contacted and Exit Meeting