

NOTICE OF VIOLATION

52.9
Copy 7 of 90
1 page

THIS DOCUMENT IS NOT TO BE REPRODUCED WITHOUT SPECIFIC APPROVAL OF IEIV
Docket No. 70-25

Energy Systems Group

As a result of the routine safeguards inspection conducted October 19-23, November 2-6, 16, 17 and November 30 - December 4, 1981 and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

10 CFR 70.51(f)(2)(ii) requires "verification of the integrity of tamperproofing devices on containers...."

Contrary to the above, the licensee did not verify the integrity of all tamperproofing seals when he physically inventoried MBA-01 (his storage vault) on November 3, 1981.

This is a Severity Level V violation (Supplement III).

Pursuant to the provisions of 10 CFR 2.201, Energy Systems Group is hereby required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; and (2) the corrective steps which will be taken to avoid further items of noncompliance. Consideration may be given to extending your response time for good cause shown.

date: January 15, 1982

B. L. Brock
B. L. Brock, Chemist

10 CFR [REDACTED] SECTION

357