DESIGNATED ORIGINAL



Certified By Mar

Public Service Electric and Gas Company P.O. Sox E. Hancocks Bridge, New Jersey 08038

Salam Generating Station

August 10, 1982

Mr. R. C. Haynes
Regional Administrator
USERC
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

50-311

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 82-070/01P SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Monday, August 9, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a service water leak was discovered inside the Containment Building, on Mo. 24 Containment Pan Coil Unit. The leak rate was approximately 0.5 gallons per minute, and the leak has been isolated.

An investigation is in progress, and a detailed report will 'be submitted in the time period specified by IE Bulletin 80-24.

Sincerely yours,

p.9. refidence

H. J. Midura General Manager -Salem Operations

RF:ks

CC: Distribution